Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mine Name: **South Sunlight**Mine ID: **702**

Navajo AUM North Central Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.039.0020

April 2012

| Part I | Site Identification, Location and Status | | | | | |
|--|--|----------------|--|--------------------|------------|--|
| Site Names and ID numbers as applicable | | | | | | |
| Mine ID: | 702 | | | | | |
| Map ID: | NC43 | | | | | |
| CERCLIS: | NNN000909306 | | | | | |
| Navajo Abandoned Mine Land Reclamation Program: NA-0220 | | | | | | |
| Local name / | Aliases: South S | Sunlight Decli | ine | | | |
| Chapter and l | local area: Olja | to | | | | |
| County: Nava | ajo | State: | AZ | | | |
| Lat/Long: | 36.9445876485 | N / -110.2888 | 312657 V | V | | |
| Nearby road | and highway: I | ndian Route 6 | 420 I | Local Post Office: | Oljato, AZ | |
| Surface Land Status: check one or more and provide ownership and contact information below | | | | | | |
| Tribal Trust l Private Bureau of La State | | | Public la Tribal F Allotme Fee land | Fee Land ont | | |
| Subsurface Mineral Rights: | | | | | | |
| No information on subsurface mineral rights ownership was found in the EPA/AUM Database. | | | | | | |

Claim and operator information:

Historical documents identified the operator of the mine in 1955 as Roy and Betty Gray, and from 1961 to 1965 as Industrial Uranium Company. No additional historical ownership / lease information was identified in the EPA / AUM database.

Number of residential structures within 200 feet of mine: None

Part II Summary of Radiological Readings

Mine ID: 702

Highest gamma radiation measurement: 826,803 counts per minute (cpm)


Background Average: 10,351 cpm **Two Times Background:** 20,702 cpm

Describe any other radiological measurements:

A total of 3,520 gamma radiation measurements were collected from the mine site, ranging from 7,090 cpm to 826,803 cpm. Maximum levels of approximately 825,000 cpm were found in the vicinity of the waste rock. The measurements are represented in Figures 1 and 2.

Distribution Chart and Statistics:

| Site Gamma Radiation Statistics | | | | |
|--|---------|--|--|--|
| Number of Readings | 3,520 | | | |
| Minimum (cpm) | 7,090 | | | |
| Maximum (cpm) | 826,803 | | | |
| Mean (cpm) | 88,748 | | | |
| Median (cpm) | 16,936 | | | |
| Standard Deviation | 156,790 | | | |



Part III Status of Reclamation and Mine Waste

Mine ID: 702

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0220

NAMLRP Mine features: 1 Portal

The following information was obtained from field observations collected during the 2011 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:

Adits:

None Observed

Waste Piles:

Waste piles located in center near where old road

Pits:

None Observed

Shafts:

None Observed

Other Debris and Mine Features:

Mining camp waste (cans, bottles with a few waste piles and debris) found in central area near the road and in southwest corner of the site

Part IV Site Observations and Environs

Observed Residential Structures (number and human habitation status of structures at the following distances from the mine site):

0 to 200 feet: None Observed

200 feet to 0.25 mile: None Observed

Observed Public or Commercial Structures (schools, clinics, Chapter Houses, places of business and any other structures used by members of the community at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed Water Sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine site):

0 to 0.25 miles: 750 ft NW - Water Well 8K-433

0.25 miles to 4 miles: 0.5 mi SW - Well (519)

Sensitive Environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

None observed

Known Site History (information from interviews with Chapter officials and residents and database review, includes: mine ownership, type of mining operation, period of operation, known amount of production, and any other information provided):

The South Sunlight mine claim consists of an area of 78,352 m². The mine was identified as being operational from 1962 to 1965. While operational, the mine had a total reported production volume of 28,645 tons. No additional historical ownership / lease information was identified in the EPA / AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity?

Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? Yes

Structures:

Were any structures observed within 200 feet of the mine? $\ensuremath{\mathrm{No}}$

Potential Drinking Water Sources:


Were any potential drinking water sources observed within 4 miles of the mine? Yes


Reclamation:


Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?


Yes


Part VI Photos



















Part VII Contact Reports and Information

| Name: | Eugene Esplain |
|----------------------------------|------------------------------------|
| Title or official role (if any): | Navajo EPA Superfund Program |
| Telephone number: | (928) 871-7331 |
| Address: | PO Box 2946, Window Rock, AZ 86515 |
| Information provided: | Lead Regulatory Agency |
| | |
| | |
| Name: | |
| Title or official role (if any): | |
| Telephone number: | |
| Address: | |
| Information provided: | |
| | |
| | |
| Name: | |
| Title or official role (if any): | |
| Telephone number: | |
| Address: | |
| Information provided: | |
| | |

